



		<h1 style="text-align: center;">Fiber Inspection</h1>			
<b>Inspection Date</b> 3/17/2015 12:25:36 PM <b>Company Name</b> <b>Location</b> <b>Operator</b>					
<b>Fiber Information</b>					
<b>File Name</b> ED1_prt23_TX.pdf <b>Fiber Type</b> Simplex <b>Job ID</b> <b>Fiber ID</b> 22 <b>Comments</b> ED1 23 TX					
<b>Inspection Summary</b>					
<b>Profile Name</b>		SM UPC (IEC-61300-3-35)			
<b>Zone</b>		<b>Defects</b>		<b>Scratches</b>	
Zone A (0 - 25)		PASS		PASS	
Zone B (25 - 120)		PASS		PASS	
Zone C (120 - 130)		PASS		PASS	
Zone D (130 - 250)		PASS		PASS	
<b>Low Magnification</b>			<b>High Magnification</b>		
					
<b>Analysis Details</b>					
© 2015 JDS Uniphase Corporation. All rights reserved.				Page #1	